DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-013618 Address: 333 Burma Road **Date Inspected:** 27-Apr-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Li Yang No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No **Weld Procedures Followed:** Yes No N/A Yes N/A **Qualified Welders:** No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG Segment**

Summary of Items Observed:

On this date Caltrans OSM Quality Assurance (QA) Inspector, Dan Hernandez was present during the times noted above to observe the fit up, welding and related activities associated with the fabrication of the San Francisco Oakland Bay Self Anchored Suspension Bridge at Zhenhua Port Machinery Company (ZPMC) facility on Changxing Island.

OBG Trial Assembly Yard

Segment 8AE

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as CA048-002. The welder is identified as #037743 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as CA048-001. The welder is identified as #067829 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

Segment 8BE

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as CA052-006. The welder is identified as #037743 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

This QA Inspector observed Shielded Metal Arc Welding (SMAW) in progress of a Complete Joint Penetration (CJP) weld joint. The Weld joint is designated as CA052-005. The welder is identified as #067829 and was observed welding in the 4G (overhead) position using approved Welding Procedure Specification WPS-B-P-2214-TC-U4b-FCM-1.

ZPMC Quality Control (QC) Inspector is identified as Wang Li Yang. QA Inspector observed QC Inspector verify welding parameters. The welding variables recorded by QC appeared to comply with the Applicable WPS.

BAY 19

This QA observed Welder Qualifications of the following ZPMC personnel, process and position:

Flux Cored Arc Welding, 4G WPS-B-T-2234-B-U2a-F-1

- #1 Guo Hong Bin
- #2 Yu Fang Fu
- #3 Yu Fang Run
- #4 Shen Bin Fa
- #6 Tang Hai Jun
- #7 Chen Ru Quan
- #8 Feng Qi Yuan
- #9 Yang Yang
- #10 Zhou De Hui
- #11 Xu Da Cai
- #12 Qu Huo Lin
- #14 Zhou De Quan

Shield Metal Arc Welding, 4G WPS-B-P-2214-B-U2a-1

- #15 Sun Cheng Jin
- #16 Cao Yi Hui
- #17 Sun Cheng Zhuo

Shield Metal Arc Welding, 4F WPS-B-P-2214 (Tack weld)

- #18 Zhou Hai Yang
- #19 Shao Wen Lin
- #20 Shao Xiao Bin
- #21 Shao Jie

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Welder Qualifications were administered by ZPMC CWI Zhou Cheng.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No relevant conversations.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, 150-0042-2372, who represents the Office of Structural Materials for your project.

Inspected By:	Hernandez,Dan	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer